





## WB-1060 INVENTORY LIST

<u>TUXEDO CODE</u>	<u>DESCRIPTION</u>	<u>M. REF</u>	
WB-1030-7003	Belt	105	
WB-1030-7007	Pulley	104	
WB-1030-7008	Pin, Retaining	103	
WB-1030-7009	Motor	102	
WB-1030-7010	Cable	137	
WB-1030-7011	Transformer	138	
WB-1030-7012	Spacer, Nylon	134	
WB-1030-7014	Paper, Insulated	132	
WB-1030-7015	Resistor	133	
WB-1030-7016	Clip	131	
WB-1030-7017	Screw, M4 X 10	136	
WB-1030-7020	Handle, Wheel Balancer	158	
WB-1030-7021	Cone, # 1	155	
WB-1030-7022	Cone, # 2	156	
WB-1030-7023	Cone, # 3	157	
WB-1030-7024	Gauge, Width	160	
WB-1030-7025	Screw, M6 X 16	161	
WB-1030-7026	Scale Handle	162	
WB-1030-7027	Rod, Scale	163	
WB-1030-7028	Guide, Scale	164	
WB-1030-7029	Circlip, #25	165	
WB-1030-7030	Support, Scale	166	
WB-1030-7031	Screw, M5 X 12	167	
WB-1030-7032	Guide, Scale End	168	
WB-1030-7033	Spring	169	
WB-1030-7034	Flat Washer #6	170	
WB-1030-7035	Hammer, Balance Weight	154	
WB-1030-7040	Spring	112	
WB-1030-7041	Tube for Hood	113	
WB-1030-7043	Microswitch	126	
WB-1030-7050	Lock Ring, Frame	114	
WB-1030-7051	Nut, M6	116	
WB-1030-7052	Screw, M6 X 40	115	
WB-1030-7053	Screw, M6 X 16	117	
WB-1030-7054	Locknut, M10	118	
WB-1030-7056	Screw, M10 X 50	119	
WB-1030-HD-1	Hood	121	
WB-1030-7058	Screw, M5.5 X 25	122	
WB-1030-7059	Switch, Main	159	
WB-1030-7060	Screw, M10 X 160	201	
WB-1030-7061	Terminal, Threaded Rod	202	
WB-1030-7062	Flange	203	
WB-1030-7063	Shaft, Main	204	
WB-1030-7064	Flat Washer #8	205	
WB-1030-7065	Screw, M8 X 25	206	
WB-1030-7066	Pulley	207	
WB-1030-7067	Screw, M5 X 10	208	
WB-1030-7068	Cover, Bearing	209	
WB-1030-7069	Screw, M5 X 16	210	

## WB-1060 INVENTORY LIST

<u>TUXEDO CODE</u>	<u>DESCRIPTION</u>	<u>M. REF</u>	
WB-1030-7070	Bracket	211	
WB-1030-7071	Washer, Elastic #4	212	
WB-1030-7072	Flat Washer, #4	213	
WB-1030-7073	Screw, M4 X 8	214	
WB-1030-7074	Disk, Phase	215	
WB-1030-7075	Circlip, #25	216	
WB-1030-7076	Bearing, 6005Z	217	
WB-1030-7077	Bearing, 6006Z	219	
WB-1030-7078	Spindle	220	
WB-1030-7079	Flat Washer, #10	231	
WB-1030-7080	Washer, Elastic #10	232	
WB-1030-7081	Screw, M10 X 20	233	
WB-1030-7083	Encoder Board	228	
WB-1030-7084	Adjusting Plate	226	
WB-1030-7085	Rod, Eye	234	
WB-1030-7086	Nut, M10	235	
WB-1030-7087	Washer	236	
WB-1030-7088	Sensor, Piezo	237	
WB-1030-7089	Cable of Sensor	238	
WB-1030-7090	Nut, M10	239	
WB-1030-7091	Rod, Thread	240	
WB-1030-7092	Screw, 2.2 X 15, Self Tapping	241	
WB-1030-7093	Cover	242	
WB-1030-7094	Spring	243	
WB-1030-7095	Plate	244	
WB-1030-7096	Cover, Plastic	245	
WB-1030-7097	Nut	246	
WB-1030-7098	Pin, 5 Dia X 35	247	
WB-1030-7099	Pin, 5 Dia X 20	248	
WB-1030-7100	Handle, Body	249	
WB-1030-7101	Ring, Protecting	250	
WB-1030-7102	Bowl, Rubber	251	
WB-1030-7103	Spring	252	
WB-1030-7104	Speed Nut	255	
WB-1030-7105	Washer, Elastic #4	221	
WB-1030-7106	Flat Washer #3	225	
WB-1030-7107	Washer, Elastic #3	224	
WB-1030-7108	Nut, M3	223	
WB-1030-7109	Screw, M4 X 10	222	
WB-1030-7110	Accessory Kit	N/A	
WB-1030-7111	Nut, M4	229	
WB-1030-7112	Flat Washer #4	230	
WB-1030-7113	Scale Assy.	171	
WB-1030-7115	Cone Assy.	173	
WB-1030-7116	100 Gram Weight	N/A	
WB-1030-7117	Complete Shaft	253	
WB-1030-7118	Sensor Assy.	254	
WB-1030-7119	Circlip #30	218	
WB-1030-7120	Screw, M3 X 8	227	

